



COUNTY OF KENOSHA

COUNTY CLERK

Regi Bachochin



1010 - 56th Street
Kenosha WI 53140
(262) 653-2552
Fax: (262) 653-2564

CLAIM AGAINST KENOSHA COUNTY

FULL NAME Dina Perrine-Meizer DATE 5-12-21

ADDRESS 9603-49th Ct.
Pleasant Prairie WI 53158

TELEPHONE NUMBER: Home: 262 909 6493
Work: _____

DATE & TIME OF ACCIDENT OR LOSS May 8, 2021

LOCATION OF ACCIDENT Hwy 50 Westbound @ temp. off ramp to Strawberry Creek.

DESCRIPTION OF ACCIDENT OR LOSS Front passenger side Rim tire ruined from hitting pothole. Vehicle forced to have half car on shoulder when exiting to Strawberry Creek. At 25mph. Its quick & should have never been there. Caves are all over the place exit is not clear. As seen in photos Rim is bent outward which is clear indication of a pothole hit not anything else. If construction crew weren't out this would have never happened. Also entire area has since been blacktopped.

WITNESS: Name N/A
Address _____
Phone _____

AMOUNT OF CLAIM (damages) \$ 2500.00 see estimate

CLAIMANT'S SIGNATURE Dina Perrine Meizer

Please attach receipts, estimates, and/or other supporting data to this form.

RETURN THIS FORM TO: KENOSHA COUNTY CLERK
1010 - 56TH STREET
KENOSHA WI 53140





DOT HNP D400 3220

Continental



MADE IN GERMANY



International Autos

KNOW YOUR VEHICLE™

FITNESS INSPECTION & TREATMENT PLAN

MultiPoint Inspection

Marcus Meinzer

9603 49TH CT
PLEASANT PR, WI 53158-6549
(262) 844-4386
MARCUS.MEINZER@GMAIL.COM

Lucas England

Service Consultant

414-727-6745

LENGLAND@IAMILWAUKEE.COM

B. Hamilton

Certified Technician

YOUR VEHICLE



Year 2021	Make Audi	Model Q8	Engine Type 3.0L V6 DOHC (DI)
Odometer 2,727	VIN # WA1FVAF19MD006356	License #	Date 5/13/2021



Recommended Services

Our technicians recommend the following services for your vehicle.

Original Customer Requests	Status	Cost	Deferred	Approved
A. CUSTOMER STATES SHE HIT A POTHOLE AND CAUSED DAMAGE TO THE RIGHT FRONT CORNER AND POTENTIALLY THE RIGHT REAR. PLEASE CHECK AND ADVISE.				X
NEED RIM (RIGHT FRONT RIM BENT)		\$1,699.46		
B. Complimentary Multi-Point Vehicle Report		\$0.00		X
Subtotal		\$1,699.46		
Inspection Recommendations	Status	Cost	Deferred	Approved
Mount and balance 1 new tire (right front) (Found damage to sidewall)	Fail	\$492.95		See AI-32
Perform four (4) wheel alignment (Found damage to sidewall)	Fail	\$200.00		See AI-44
Subtotal		\$692.95		
Totals, Taxes and Fees		Cost	Deferred	Approved
Estimate Subtotal		\$2,392.41	\$0.00	\$0.00
Shop Supplies		\$5.00		\$0.00
Tax		\$131.58		\$0.00
Estimate Total		\$2,528.99		\$0.00

For "See AI-" items  see the "Additional Information" section 

INTERNATIONAL AUTOS

2400 S.108th Street
Milwaukee, WI 53227

www.internationalautogroup.com

Phone: (414) 543-3000
Fax: (414) 543-5150

30% HANDLING CHARGE ON RETURNED ITEMS.
NO RETURNS ON ELECTRICAL OR SPECIAL ORDERED ITEMS.
NO RETURNS ON AIRBAGS, PRETENSIONERS OR STRUCTURAL METAL.
RETURNS MUST MEET MANUFACTURER'S PACKAGING SPECIFICATIONS.

THE ONLY WARRANTIES APPLYING TO THIS PART(S) ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER. THE SELLING DEALER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THIS PART(S) AND/OR SERVICE. BUYER SHALL NOT BE ENTITLED TO RECOVER FROM THE SELLING DEALER ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT, OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

DATE ENTERED 11 MAY 21	YOUR ORDER NO.	DATE SHIPPED 12 MAY 21	INVOICE DATE	INVOICE NUMBER QR180736	09:24
---------------------------	----------------	---------------------------	--------------	----------------------------	-------

S
O
L
D
T
O

ACCOUNT NO. C62493

P
A
R
T
S
Q
U
O
T
E
S
H
I
P
T
O

MARCUS MEINZER
9603 49TH CT
PLEASANT PR, WI 53158-6549

*** R O P A R T S Q U O T E - DO NOT PAY ***
PAGE 1 OF 1

QR180736

SHIP VIA	SLSM. ZG	B/L NO. (262)844-4386	TERMS	F.O.B. MILWAUKEE, WI
----------	-------------	--------------------------	-------	-------------------------

QTY	SHIP	B.O.	PART NUMBER	DESCRIPTION	LIST	NET	AMOUNT
RO Quote for Service Repair Order: 626814 Service Advisor: 8607 Vehicle: MD006356							
Part(s) quoted on Line A CUSTOMER STATES SHE HIT A POTH							
1	1	0	4M8-601-025-Q	WHEEL ASO	1684.46	1684.46	1,684.46
1	1	0	DT0-354-959	CROSSCONT ASO	438.00	438.00	438.00
Parts quoted on RO# 626814 *** R O P A R T S Q U O T E - DO NOT PAY ***							

Parts Dept. Hours:
Monday - Friday
7:30 am - 5:30 pm
Saturday
9:00 am - 1:00 pm

We stock and or
order parts for:
Audi
BMW
Mini
Mercedes Benz

Thank You!

NO RETURNS ON SPECIAL ORDER, AIRBAGS
OR ELECTRICAL PARTS. 30% RESTOCK
FEE ON ALL OTHER PARTS.
CORES MUST BE RETURNED IN FACTORY BOX
* * THANK YOU FOR YOUR BUSINESS * *

MISC SUPPLIES

PARTS	2,122.46
SUBLET	
FREIGHT	0.00
SALES TAX	0.00
TOTAL	

Copyright 2014 CDK Global, LLC

THANK YOU!

CUSTOMER COPY

CUSTOMER SIGNATURE

OFFICE COPY

X

\$0.00

INTERNATIONAL AUTOS

2400 S.108th Street
Milwaukee, WI 53227

www.internationalautogroup.com

Phone: (414) 543-3000
Fax: (414) 543-5150

NO RETURNS WITHOUT THIS INVOICE. 30% HANDLING CHARGE ON RETURNED ITEMS.
NO RETURNS ON ELECTRICAL OR SPECIAL ORDERED ITEMS.
NO RETURNS ON AIRBAGS, PRETENSIONERS OR STRUCTURAL SHEET METAL.
RETURNS MUST MEET MANUFACTURER'S PACKAGING SPECIFICATIONS.

THE ONLY WARRANTIES APPLYING TO THIS PART(S) ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER. THE SELLING DEALER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THIS PART(S) AND/OR SERVICE. BUYER SHALL NOT BE ENTITLED TO RECOVER FROM THE SELLING DEALER ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT, OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

DATE ENTERED 11 MAY 21	YOUR ORDER NO.	DATE SHIPPED 12 MAY 21	INVOICE DATE	INVOICE NUMBER QR180736	09:24
---------------------------	----------------	---------------------------	--------------	----------------------------	-------

S
O
L
D
T
O

ACCOUNT NO. C62493

P
A
R
T
S
Q
U
O
T
E
S
H
I
P
T
O

MARCUS MEINZER
9603 49TH CT
PLEASANT PR, WI 53158-6549

*** R O P A R T S Q U O T E - DO NOT PAY ***
PAGE 1 OF 1

QR180736

SHIP VIA	SLSM. ZG	B/L NO. (262)844-4386	TERMS	F.O.B. MILWAUKEE, WI
----------	-------------	--------------------------	-------	-------------------------

QTY	SHIP	B.O.	PART NUMBER	DESCRIPTION	LIST	NET	AMOUNT
RO Quote for Service Repair Order: 626814 Service Advisor: 8607 Vehicle: MD006356							
Part(s) quoted on Line A CUSTOMER STATES SHE HIT A POTH							
1	1	0	4M8-601-025-Q	WHEEL ASO	1684.46	1684.46	1,684.46
1	1	0	DT0-354-959	CROSSCONT ASO	438.00	438.00	438.00
Parts quoted on RO# 626814 *** R O P A R T S Q U O T E - DO NOT PAY ***							

NO RETURNS ON SPECIAL ORDER, AIRBAGS
ELECTRICAL PARTS. 30% RESTOCK
FEE ON ALL OTHER PARTS.
CORES MUST BE RETURNED IN FACTORY BOX
* * THANK YOU FOR YOUR BUSINESS * *

MISC SUPPLIES

PARTS	2,122.46
SUBLET	
FREIGHT	0.00
SALES TAX	0.00
TOTAL	